

```

WRUNP: LEA TDRUN, A0
        BSR XPTET

```

) ⊗

```

WRUNP: BSR RLIGNE

```

demande ligne

RUN...

```

WRUNR: JMP WRUN
        BSR X9
        JMP WRUN

```

RUN

```

WDEBUGP: LEA TDEBUG, A0
          BSR XPTET

```

) ⊗ "debug"

```

WDEBUGP: BSR RLIGNE

```

demande ligne

debug...

```

WDEBUGP: BSR X9
WDEBUGP: JMP WG

```

debug

```

WDEBUGO: MOVEQ #0, D0
          BSR X9
          JMP HI100

```

debug 0